Message Text

UNCLASSIFIED

PAGE 01 SAN SA 04165 081539Z

45

ACTION FBO-01

INFO OCT-01 ARA-10 ISO-00 /012 W

----- 068162

P 081515Z NOV 73

FM AMEMBASSY SAN SALVADOR

TO SECSTATE WASHDC PRIORITY 4065

UNCLAS SAN SALVADOR 4165

E.O. 11652 N/A

TAGS: ABLD ES

SUBJ: AIR CONDITIONING TROUBLES IN EMBASSY

TO:FBO

- 1. HIGH BEARING TEMPERATURE ON COMPRESSOR OF NUMBER TWO AIR-CONDITIONER (TONRAC) UNIT IS CAUSING THE AUTOMATIC CUT-OFF IN THE COMPRESSOR TO TRIP SHUTTING DOWN THE UNIT. WE SUSPECT COMPRESSOR MAY BE BAD AND NEED EXPERT TECHNICIAN FAMILIAR WITH THIS EQUIPMENT TO ADVISE US. (NO COMPETENT SPECIALIST OR TECHNICIAN WE CONSIDER QUALIFIED AVAILABLE LOCALLY.)
- 2. TONRAC WAS ORIGINALLY MANUFACTURED BY IDEAL STANDARD WHO HAS CEASED PRODUCING AND SERVICING THIS EQUIPMENT. PARTS AND SERVICE NOW BEING PROVIDED BY MECHAN-ELECT INTERNATIONAL, INC. OF ATLANTA, GEORGIA. WE SPOKE WITH MR. WAYNE, SERVICE MANAGER OF MECHAN-ELECT, WHO WAS AGREEABLE TO SENDING ENGINEER TO EXAMINE AND POSSIBLY REPAIR THE COMPRESSOR. THIS IS ESTIMATED TO COST APPROXIMATELY \$630.00 BROKEN DOWN AS FOLLOWS:
- 1. AIRFARE (ECONOMY) \$276.00
- $2.~{\rm PER~DIEM~(APPROX.~2~DAYS)}~54.00$
- 3. APPROX. 15 HOURS OF WORK FOR ENGINEER AT \$20.00 PER HOUR \$300.00

TOTAL \$630.00

3. POST CANNOT FUND THIS FROM ITS ALLOTMENT. REQUEST ADVISE SOONEST OTHERWISE EMBASSY MAY SOON BE WITHOUT AID-CONDITIONING. MOSKOWITZ UNCLASSIFIED

UNCLASSIFIED

PAGE 02 SAN SA 04165 081539Z

Declassified/Released	US De	nartment (of	State	FΩ	SI	stematic	Review	30	JUIN.	2005
		partificit	JI.	Olaic	-	\cup \vee	Sterriatio	11011011	50	JUIN	2000

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 08 NOV 1973 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Authority: n/a Disposition Case Number: n/a

Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:

Document Number: 1973SANSA04165 Document Source: CORE Document Unique ID: 00

Drafter: n/a Enclosure: n/a Executive Order: N/A Errors: N/A Film Number: n/a From: SAN SALVADOR Handling Restrictions: n/a

Image Path:

Legacy Key: link1973/newtext/t19731146/aaaabhyn.tel Line Count: 60

Locator: TEXT ON-LINE

Office: ACTION FBO Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a

Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: Previous Classification: n/a Previous Handling Restrictions: n/a Reference: n/a Review Action: RELEASED, APPROVED Review Authority: cunninfx

Review Comment: n/a Review Content Flags: Review Date: 01 FEB 2002

Review Event:

Review Exemptions: n/a
Review History: RELEASED <01-Feb-2002 by elbezefj>; APPROVED <21 FEB 2002 by cunninfx>

Review Markings:

Declassified/Released US Department of State EO Systematic Review 30 JUN 2005

Review Media Identifier: Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: AIR CONDITIONING TROUBLES IN EMBASSY TO:FBO

TAGS: ABLD, ES To: STATE

Type: TE

Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005